

Rosemary Inn, Indiana Cabin (Bldg. No. 375)  
Olympic National Park  
Barnes Point, Lake Crescent  
Port Angeles Vicinity  
Clallam County  
Washington

HABS No. WA-185-D

HABS  
WASH  
5-POANN,  
2D-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA



Historic American Building Survey  
National Park Service  
Western Region  
Department of the Interior  
San Francisco, California 94107

HABS  
WASH  
5-POAN.V,  
2D-

NATIONAL PARK SERVICE  
Department of the Interior

HISTORIC AMERICAN BUILDING SURVEY  
ARCHITECTURAL DATA FORM

STATE WASHINGTON	COUNTY CLALLAM	TOWN OR VICINITY Approximately 20 miles southwest of Port Angeles
HISTORIC NAME OF STRUCTURE (include source for name) Rosemary Inn , "Indiana" Cabin		HABS NO. WA-185-D
SECONDARY OR COMMON NAMES OF STRUCTURE Bldg. No. 375		
COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park.		
DATE OF CONSTRUCTION (include source) pre-1926 (Historic Structure Report)	ARCHITECT(S) (include source) Builder and Craftsman: John Daum (HRS, 1983)	
SIGNIFICANCE (architectural and historical, include original use of structure) This cabin was constructed as an integral part of the Rosemary Inn Complex. It contributes to the overall character of the rustic, picturesque resort ensemble and possesses integrity of design, materials, workmanship, location, setting, feeling and association.		
STYLE (if appropriate) Craftsman-style cottage		
MATERIAL OF CONSTRUCTION (include structural systems) Wood-frame construction set on 6 x 6 wood posts on concrete piers.		
SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable) Square: 16' x 16'		
EXTERIOR FEATURES OF NOTE 1-story; wood-shingled gable roof with extended eaves and exposed rafter ends; knee braces support eaves on gable ends; recessed entry with shed roof overhang supported by knee braces on south; shiplap siding with unpainted wood shingles above and cedar bark applied beneath gables; single light casement windows; plain corner boards, sill and window and door trim; sidelight (painted) flanking panelled wood entry door.		
INTERIOR FEATURES OF NOTE (describe floor plans if not sketched) Painted floor boards; ceiling has 3 1/4" bevelled board siding; 5 1/4" vertical board wainscotting with horizontal bevelled boards above.		
MAJOR ALTERATIONS AND ADDITIONS, WITH DATES Complete rehabilitation of cabin, 1987		
PRESENT CONDITION AND USE Excellent; seasonal housing		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.) Historic Structure Report, 1986 Historic Resource Study, 1983 Historic Building Inventory, 1983 National Register Listing, 1979		
COMPILER, AFFILIATION Gretchen A. Luxenberg, National Park Service		DATE July, 1988



Indiana Building #375